# MALMO



CODING
- 336103



ISO 9001:2015

nuhoom.com

Read the instructions carefully. Remove all the wrappings , staples and straps from the carton. Refer to the hardware and furniture part list for guidance. Make sure that you have all the parts before you start assembling. Place all the wooden furniture parts on a clean, flat and soft surface, such as a carpet or rubbermat to prevent scratches.

CAUTION
KEEP ALL THE PARTS OUT OF CHILDREN'S REACH.

| HARDWARE | | |
|---|---|---|
| A | MINI FIX A1 A2 A3 | 14 SETS |
| B | M8 X 30MM WOOD DOWEL | 24 PCS |
| C | M6 X 50MM CSK CAP WOOD SCREW | 10 PCS |
| D | ALLEN KEY M4 | 1 PC |
| E | PAN HEAD SCREW M4 X 12MM | 8 PCS |
| F | METAL BRACKET | 4 PCS |
| G | M3.5 X 16MM C.B SCREW | 4 PCS |
| H | PVC HANDLE 7050.96 | 2 PCS |
| I | METAL SHELF SUPPORT | 8 PCS |
| J | STUD 192 WITH SCREW J1 J2 | 8 PCS |
| K | ROSE METAL LEG | 6 PCS |
| | TIPPING PACK WITH AI | 2 SETS |

| **SELF-PREPARED TOOLS:** Tools below are NOT included in package. | |
|---|---|
| SCREWDRIVER | HAMMER |

| PART LIST | | QTY |
|---|---|---|
| 1 | TOP PANEL | 1 PC |
| 2 | BOTTOM PANEL | 1 PC |
| 3 | SIDE PANEL (L) | 1 PC |
| 4 | SIDE PANEL (R) | 1 PC |
| 5 | CENTER PANEL (L) | 1 PC |
| 6 | CENTER PANEL (R) | 1 PC |
| 7 | MIDDLE PANEL | 1 PC |
| 8 | SIDE SHELF PANEL | 2 PCS |
| 9 | BACK SIDE | 2 PCS |
| 10 | BACK PANEL (C) | 1 PC |
| 11 | BACK PANEL (L/R) | 2 PCS |
| 12 | SLIDING DOOR | 2 PCS |

CODING
- 336103



ISO 9001:2015

nuhoom.com



# MALMO



CODING
- 336103



ISO 9001:2015
Reg. No. 660435-1-MY-1-QMS

## nuhoom.com

### STEP 1

SCREWDRIVER REQUIRED

- Insert hardware **A2** onto panel **(1)**.
  (Repeat 10 times.)
- Insert hardware **B** onto panel **(3)** and **(4)**.
  (Repeat 8 times.)




### STEP 2

SCREWDRIVER REQUIRED

- Insert hardware **A2** onto panel **(5)** and **(6)**.
  (Repeat 4 times.)
- Insert hardware **B** onto panel **(5), (6) (7)** and **(9)**.
  (Repeat 16 times.)




### STEP 3

SCREWDRIVER REQUIRED

- Insert hardware **A1** onto panel **(7)**.
- Attach panel **(5)** and **(6)** to panel **(7)**.
- Insert all hardware **A2** into **A1**.
- Rotate all **A1** until tight.
- Apply **A3** onto all **A1**.
  (Repeat 4 times.)




### STEP 4

SCREWDRIVER REQUIRED

- Insert hardware **A1** onto panel **(5)** and **(6)**.
- Attach panel **(5)** and **(6)** to panel **(1)**.
- Insert all hardware **A2** into **A1**.
- Rotate all **A1** until tight.
- Apply **A3** onto all **A1**.
  (Repeat 4 times.)




### STEP 5

SCREWDRIVER REQUIRED

- Insert hardware **A1** onto panel **(3), (4)** and **(9)**.
- Attach panel **(3), (4)** and **(9)** to panel **(1)**.
- Insert all hardware **A2** into **A1**.
- Rotate all **A1** until tight.
- Apply **A3** onto all **A1**.
  (Repeat 6 times.)




### STEP 6

- Insert the panel **(10)** and **(11)** along the slot.
  (Repeat 3 times.)



CODING
- 336103



ISO 9001:2015

nuhoom.com

STEP 7

HARDWARE D

- Connect panel **(2)** to panel **(3)**, **(4)**, **(5)**, **(6)** and **(9)** by using hardware **C** and **D**.
(Repeat 10 times.)




STEP 8

SCREWDRIVER REQUIRED

- Insert hardware **J1** into slot at panel **(1)**, **(2)**, **(3)** and **(4)**.
- Assemble hardware **J1** by using hardware **J2**.
(Repeat 8 times.)




STEP 9

- Assemble hardware **K** into bottom of panel **(2)**.
(Repeat 6 times.)




STEP 10

Insert hardware **I** into mounting positions on panel **(3)**, **(4)**, **(5)** and **(6)** by hand.
(Repeat 8 times.)




STEP 11

- Assemble the panel **(8)** into between panel **(3)** and **(5)**.
- Assemble the panel **(8)** into between panel **(4)** and **(6)**.




STEP 12

SCREWDRIVER REQUIRED

- Fix hardware **H** onto panel **(12)** by using hardware **G**.
(Repeat 2 times for each hardware.)



CODING
- 336103



ISO 9001:2015
Reg. No. 600435-1-MY-1-QMS

nuhoom.com

STEP 13
- Insert panel **(12)** into grooves at panel **(1)** and **(2)**.




STEP 14
- Insert panel **(12)** into grooves at panel **(1)** and **(2)**.




STEP 15
- Assemble the hardware **F** onto panel **(1)** and **(2)** by using hardware **E**.
(Repeat 2 times for each hardware.)

SCREWDRIVER REQUIRED