
CODING - 653027



ISO 9001:2015

nuhoom.com


Read the instructions carefully. Remove all the wrappings, staples and straps from the carton. Refer to the hardware and furniture part list for guidance. Make sure that you have all the parts before you start assembling. Place all the wooden furniture parts on a clean, flat and soft surface, such as a carpet or rubbermat to prevent scratches.

CAUTION
KEEP ALL THE PARTS OUT OF CHILDREN'S REACH.


HARDWARE			
Α	MINI FIX A1 A2 (((C - (3) A3 - (-)	16 SETS	
В	M8 X 30MM WOOD DOWEL	18 PCS	
С	M6 X 50MM CSK CAP WOOD SCREW	6 PCS	
D	ALLEN KEY M4	1 PC	
Е	M4 X 25MM C.B SCREW	8 PCS	
F	5/8 NAIL 0	15 PCS	
G	5/8 PVC NAIL LEG	4 PCS	

PART LIST		QTY
1	TOP PANEL	1 PC
2	TOP BONE	1 PC
3	MIDDLE PANEL	1 PC
4	CENTER PANEL	1 PC
5	SIDE PANEL (L)	1 PC
6	SIDE PANEL (R)	1 PC
7	FRONT PANEL	1 PC
8	BACK PANEL	1 PC

SELF-PREPARED TOOLS: Tools below are NOT included in package.			
SCREWDRIVER	HAMMER		




CODING - 653027




ISO 9001:2015

2/2 nuhoom.com





CODING - 653027



ISO 9001:2015

nuhoom.com

Read the instructions carefully. Remove all the wrappings, staples and straps from the carton. Refer to the hardware and furniture part list for guidance. Make sure that you have all the parts before you start assembling. Place all the wooden furniture parts on a clean, flat and soft surface, such as a carpet or rubbermat to prevent scratches.


CAUTION KEEP ALL THE PARTS OUT OF CHILDREN'S REACH.

HARDWARE			
Α	MINI FIX A1 A2 CCC A3 A3	32 SETS	
В	M8 X 30MM WOOD DOWEL	20 PCS	
С	M3.5 X 16MM C.B SCREW	36 PCS	
D	M4 X 25MM C.B SCREW	10 PCS	
Е	M4 X 38MM C.B SCREW	8 PCS	
F	5/8 PVC NAIL LEG	10 PCS	
G	ONE HOLE L BRACKET (2MM)	4 PCS	
Н	311 KNOB	2 PCS	
ı	18" DRAWER SLIDE 11 (L/R) 12 (L/R)	2 SET	

SELF-PREPARED TOOLS: Tools below are NOT included in package.				
SCREWDRIVER	HAMMER			


PART LIST		QTY
1	HEADBOARD	1 PC
2	FOOTBOARD - 1	1 PC
3	FOOTBOARD - 2	1 PC
4	SIDE PANEL (L1)	1 PC
5	SIDE PANEL (L2)	1 PC
6	SIDE PANEL (R1)	1 PC
7	SIDE PANEL (R2)	1 PC
8	CENTER PANEL	1 PC
9	CENTER SUPPORT	1 PC
10	CENTER SUPPORT	1 PC
11	BUNKIE BOARD	4 PCS
12	DRAWER FRONT	2 PCS
13	DRAWER BACK	2 PCS
14	DRAWER SIDE (L)	2 PCS
15	DRAWER SIDE (R)	2 PCS
16	DRAWER BOTTOM	2 PCS
17	DRAWER BONE	4 PCS

CODING - 653027



ISO 9001:2015


nuhoom.com



2/5 nuhoom.com


CODING


- 653027




ISO 9001:2015

nuhoom.com





* In this step hardware A1, A2 and B are pre-inserted.




* In this step hardware A1, A2 and B are pre-inserted.

3 / 5 nuhoom.com

CODING

- 653027




ISO 9001:2015

nuhoom.com


SCREWDRIVER REQUIRED

G

- Assemble hardware **G** to panel **(2)**, **(3)**, **(6)**, **(7)** and **(8)** with hardware C. (Repeat 8 times.)




Connect headboard (1) to panel (2) by using hardware D. (Repeat 8 times.)






Assemble panel (11) into between panel (4), (5) and (6), (7). (Repeat 4 times)





STEP 10

- Insert hardware A1 onto panel (14), (15) and (17). (Repeat 12 times.)




ROTATE






STEP 11

- Fix hardware **H** onto panel **(12)** by using hardware **D**. (Repeat 2 times.)






STEP 12

SCREWDRIVER REQUIRED


- Assemble panel (13) with panel (14) and (15) by using hardware E. (Repeat 8 times.)

* In this step only show one of the drawers.



CODING

- 653027




ISO 9001:2015

nuhoom.com

STEP 13

insert the panel (16) along the slot.


(Repeat 2 times.)
* In this step only show one of the drawers.



STEP 14

- Attach panel (17) to panel (13) then attach panel (12) to panel (14), (15) and (17).

 - Insert all hardware A2 into A1.
- Rotate all A1 until tight.
- Apply A3 onto all A1. (Repeat 12 times.)
- * In this step only show one of the drawers.




* In this step hardware A1, A2 and B are pre-inserted.

STEP 15

- Assemble hardware I2 (L/R) to panel (14) and (15) by using hardware C. (Repeat 3 times for each hardware.)


* In this step only show one of the drawers.



STEP 16

SCREWDRIVER REQUIRED

- Put all the drawer in place along the drawer slides.



*Hardware I2 (L/R) shall be leaning against panel (12) when assembling.